



MISUMI Stock List

Part No : 00013611
Part No : 00013615
Part No : AB 1012 E0
Part No : 00013612
Part No : 00013613
Part No : 00013614
Part No : 00013616
Part No : 0L UMBKS15-20-M6
Part No : 1/4 - NI-SUS
Part No : 1/4-S-SUS
Part No : 100S5M350
Part No : 15104620
Part No : 1601552
Part No : 214A
Part No : 2A HOTNIFE HAND UNIT ONLY -
Part No : 3222N-L6
Part No : 412 MODEL 4C HOTWEEZERS -
Part No : 4B HOTWEEZER HAND UNIT ONLY -
Part No : 4C HOTWEEZER HAND UNIT ONLY -
Part No : 57F-30140-20S
Part No : 7241080086
Part No : AFTW20
Part No : AFU-3836-9
Part No : AH25-P2B20
Part No : AHTF18S5M100
Part No : AJKTN10-40

ADAMS INTERNATIONAL LLC USA 1275 Bloomfield Ave Unit 81 Fairfield 07004, New Jersey, the United States Phone : +1 (973) 228-4293 Fax: +1 (973) 858-0288 E-Mail: info@adamsint.net Web: <http://www.adamsllc.net/>

Get quote now ! info@adamsint.net

Part No : AJKTN12-50
Part No : AJKTN6-25
Part No : AJPDR20-180E
Part No : AJSB10-18
Part No : AJSB12-38
Part No : APMFF-T2-N2-KH
Part No : APMFF-T3-N2-KH
Part No : APMTS-T4-G3
Part No : APSSPB13-A25
Part No : APSSPB16-A25
Part No : ASPF40
Part No : ASPO3-15
Part No : ASPO3-30
Part No : ASPO5-25
Part No : ATLAM25
Part No : AW10
Part No : AWS5-15
Part No : AZEXMK40-40-M12
Part No : AZXHC20-20-M5
Part No : AZXSC40-30-M12
Part No : B-M6F
Part No : BBA-322-08RC
Part No : BCAS32
Part No : BGHK6004ZZ-50
Part No : BGS4-20
Part No : BGSB6005DD-60
Part No : BLPS10-60
Part No : BM-1022
Part No : BSP40B20-N-25
Part No : BSSE1205L-[150-450/1]
Part No : BT30-HDZ16-90
Part No : BTNM20
Part No : BVGBS2-E
Part No : C1706
Part No : CBSS5-8

ADAMS INTERNATIONAL LLC USA 1275 Bloomfield Ave Unit 81 Fairfield 07004, New Jersey, the United States Phone : +1 (973) 228-4293 Fax: +1 (973) 858-0288 E-Mail: info@adamsint.net Web: <http://www.adamsllc.net/>

Get quote now ! info@adamsint.net

Part No : CCG20-123.8-NC3.2
Part No : CFPJATD12-P11.97-L15-B10-T11-H20
Part No : CFPJDTD12-P11.97-L15-B10-T11-H20
Part No : CFUR6-16
Part No : CFURC6-16
Part No : CHE40-510
Part No : CHPL20
Part No : CHPL25
Part No : CHPL32
Part No : CJPHUZ8-11-25
Part No : CLBGHN10-36.5
Part No : CLBGHN10-39.5
Part No : CLBK6-60
Part No : CMG12-50
Part No : CMGS-L100-N
Part No : CPO53-19-25
Part No : CSH-SUSTAL-M3-3
Part No : CSN36
Part No : CVTB16
Part No : DRC35-16-10
Part No : DRC40-13-10
Part No : DRC40-13-12
Part No : DRC40-15-15
Part No : DRTK16
Part No : EA/25
Part No : ENT6-14
Part No : ENT8-15
Part No : ERJL8-203-56-P6 W1.2-N100
Part No : ESJB-250-8-6-6.5-50
Part No : EXFG1-20
Part No : FA-2C-2BF
Part No : FA-3C-1
Part No : FA-4C-1
Part No : FA-7C-1
Part No : FG-13-10

ADAMS INTERNATIONAL LLC USA 1275 Bloomfield Ave Unit 81 Fairfield 07004, New Jersey, the United States Phone : +1 (973) 228-4293 Fax: +1 (973) 858-0288 E-Mail: info@adamsint.net Web: <http://www.adamsllc.net/>

Get quote now ! info@adamsint.net

Part No : FG-26-10
Part No : FG-3H-2
Part No : FPBPA3-P4.43-L6-B3
Part No : FPBPA3-P4.43-L6-B6
Part No : FPTMA12-P15-L6-B12
Part No : FPTMD12-P15-L6-B10
Part No : FRGSS-A60-200
Part No : FRN1A2-A170-V155
Part No : FSFJCC-D20-L147-F25-M8-B22-T32-N8-S19-SC0
Part No : FSWN19-15-50
Part No : FUNTC15
Part No : FUNTC20
Part No : FUS4A8-A105-V30-Q75-N5
Part No : FWS-D49-V25-T5
Part No : GDRC40-2000
Part No : GEAB1.0-12-10-K-8
Part No : GEALB2.0-15-20-E-8
Part No : GELSMR20
Part No : GH-FC-087512
Part No : GKFGHNAGH5-P3-L3-B3-E3-A15
Part No : GMC-20P2-AC200V
Part No : GMSB8-20
Part No : GRMZ20-15-10-60-E10-F50
Part No : GSB8F-S
Part No : GSV1500-25
Part No : GSWC8
Part No : H-APHWRS1008-60-P10-WC1.30-R0.15
Part No : HBNTB6-W10-H14
Part No : HBNTS6-W10-H20
Part No : HBNTS6-W12-H20
Part No : HFSLB8-4080-3000
Part No : HHAA20S5M100
Part No : HJPTU13-L10-F15
Part No : HKHHM6-H16
Part No : HLC-20AS-ET3S2

ADAMS INTERNATIONAL LLC USA 1275 Bloomfield Ave Unit 81 Fairfield 07004, New Jersey, the United States
Phone : +1 (973) 228-4293 Fax: +1 (973) 858-0288 E-Mail: info@adamsint.net Web: <http://www.adamsllc.net/>

Get quote now ! info@adamsint.net

Part No : HOSNS196
Part No : HP100-037-1.2
Part No : HRCN42
Part No : HTBN174S3M-60
Part No : HTBN350S5M-100
Part No : HTBN415S5M-100
Part No : HTBO-S5M250-400 (2000MM)
Part No : HTPA18S2M040-K-P5
Part No : HTPA20S5M100-B-N10-BC10
Part No : HTPA28S3M060-A-P5
Part No : HTUN90S2M-40
Part No : HUPNAB10-P12-B35-L10-T20-H20-A30
Part No : HUPNDB10-P12-B35-L10-T20-H20-A30
Part No : HV8-8-2D
Part No : HXMN6
Part No : HXN15-10
Part No : HXN4-5
Part No : HXNN10-10
Part No : IBNSD-T0.5-H25-L50-A5.5-X7-P14-F15-Q60
Part No : IDP6001S-22-50
Part No : JB-400-6
Part No : JBAM10-10
Part No : JBAUFP30-P21-L16
Part No : JBAUFP30-P24-L18
Part No : JBE16-P14.00-W12.04-L8
Part No : JBHF18-P12.04-L8
Part No : JBHFP18-P12-L10
Part No : JBHFP18-P12-L29
Part No : JBHFP18-P12-L32
Part No : JBNF25-P15.05-L10
Part No : JBPE10-P8.0-W3.30-L20
Part No : JBPE16-P11-W10-L15
Part No : JBPE20-P13-W12-L10
Part No : JBPE20-P13-W12-L14
Part No : JBPE20-P13-W12-L15

ADAMS INTERNATIONAL LLC USA 1275 Bloomfield Ave Unit 81 Fairfield 07004, New Jersey, the United States
Phone : +1 (973) 228-4293 Fax: +1 (973) 858-0288 E-Mail: info@adamsint.net Web: <http://www.adamsllc.net/>

Get quote now ! info@adamsint.net

Part No : JBPE20-P13-W12-L17
Part No : JBPE20-P13-W12-L20
Part No : JBPE20-P13-W12-L31
Part No : JBPE20-P13-W12-L35
Part No : JBPE25-P20-W18-L12
Part No : JNOC40
Part No : JPLRK10-P13-B12
Part No : KES6-30
Part No : KES8-20
Part No : KES8-70
Part No : KFQTAGH8-P12-L8-B9
Part No : KHK6-AC100V-5
Part No : KQM12
Part No : KUEC20-B-W-420
Part No : L4N8X6-PT1/4
Part No : L4N8X6-PT1/8
Part No : LBHRW20
Part No : LCB03 K003M
Part No : LFB-1615
Part No : LFZB10-6
Part No : LFZB8-10
Part No : LFZB8-15
Part No : LFZB8-8
Part No : LFZF10-6
Part No : LFZF8-10
Part No : LGTC40-860-K5-P200
Part No : LHBBF30
Part No : LHCK16
Part No : LHFC30
Part No : LHFCW20
Part No : LHFCW40
Part No : LHFRW16
Part No : LHIFS8
Part No : LHIRWF25
Part No : LHMSW12

ADAMS INTERNATIONAL LLC USA 1275 Bloomfield Ave Unit 81 Fairfield 07004, New Jersey, the United States Phone : +1 (973) 228-4293 Fax: +1 (973) 858-0288 E-Mail: info@adamsint.net Web: <http://www.adamsllc.net/>

Get quote now ! info@adamsint.net

Part No : LHSS10
Part No : LLT3.5
Part No : LMU-MX16
Part No : LSBG12-308-M8-N6
Part No : LSBH17-260-F15-M10-N10
Part No : LSBWRK14-200
Part No : LXNAA15-8-F11-N12
Part No : M-10 POWER SUPPLY 110 VOLT
Part No : MA-25-43
Part No : MB208-R
Part No : MBN3-260
Part No : MBN4-275
Part No : MC02-1
Part No : MC04-2L
Part No : MC04-3S
Part No : MC07-12
Part No : MC07-S3
Part No : MCOC26-6-8
Part No : MCOCGWK38-14-20
Part No : MDKT20
Part No : MDZB8-8
Part No : MDZF8-8
Part No : MFFC-20CWN
Part No : MFMS30
Part No : MISUMI - HIFS-SS-E-40-1.5
Part No : MISUMI - HTBN656S8M-300
Part No : MISUMI - HTLA40S8M300-F-22
Part No : MISUMI - HTPA40S8M300-A-N20
Part No : MISUMI - LFZB8-6
Part No : MISUMI - LFZF8-8
Part No : MISUMI - MPBZ10-15
Part No : MISUMI - MPBZU8-8
Part No : MISUMI - NHXCCH15-5
Part No : MISUMI - RORHA30-30
Part No : MISUMI - SPA08-000J

ADAMS INTERNATIONAL LLC USA 1275 Bloomfield Ave Unit 81 Fairfield 07004, New Jersey, the United States
Phone : +1 (973) 228-4293 Fax: +1 (973) 858-0288 E-Mail: info@adamsint.net Web: <http://www.adamsllc.net/>

Get quote now ! info@adamsint.net

Part No : MISUMI - SSEBD16-230
Part No : MLNP12
Part No : MO-BS802-105-N
Part No : MODEL M-10
Part No : MPBZ8-25
Part No : MPNT16
Part No : MS312H
Part No : MSK-6H3
Part No : MSPSS6
Part No : MSRB10-2.0
Part No : MSSF4-16
Part No : MSTKD-B
Part No : MSTKD-EL
Part No : MSTKD-FB
Part No : MUSC20
Part No : MWLM PR26H7S
Part No : MYAP32-100
Part No : NB0102A-20-29-P-DRGC
Part No : NCS-163-P-CH
Part No : NFJN16-180
Part No : NHXCC10-4
Part No : NHXCC12-4.5
Part No : NHXCC15-5
Part No : NHXCC25.6
Part No : NKOSC6-16-22
Part No : NKOSJ5-30
Part No : NRLSR6-30
Part No : NRW-20-4-RM
Part No : NSXP3
Part No : OS-011M
Part No : P11EDB-DULD
Part No : P12-VMQ-70
Part No : P26-VMQ-70
Part No : P28-VMQ-70
Part No : P30-8M-20 6F

ADAMS INTERNATIONAL LLC USA 1275 Bloomfield Ave Unit 81 Fairfield 07004, New Jersey, the United States
Phone : +1 (973) 228-4293 Fax: +1 (973) 858-0288 E-Mail: info@adamsint.net Web: <http://www.adamsllc.net/>

Get quote now ! info@adamsint.net

Part No : PBG10-30
Part No : PCCGH6-21
Part No : PCCGH6-29
Part No : PETRS25-310-SC10-LKC
Part No : PETRS30-350-SC20-LKC
Part No : PFG-3.5A-NE
Part No : PFG-3.5A-SE
Part No : PFG-6-N
Part No : PJG-6-NE
Part No : PJG4
Part No : PJH-N12-15
Part No : PJH12-10
Part No : PJL5-3
Part No : PJXK5-5
Part No : PKCLCF15-51
Part No : PMXPM16
Part No : PMXYK6M
Part No : PMXYSB8
Part No : PQG-8-NE
Part No : PS-10-JM-S
Part No : PS-10A-M-S
Part No : PSEGS42-245
Part No : PSFJ30-745
Part No : PSFJ40-420
Part No : PSFJZ30_220_0_M12_N12_SC10_LKC
Part No : PSFPG12-260-F11-P9-M6-SC10
Part No : PSFPGH16-755-F10-P12-M8-SC25
Part No : PSFUT8-120-M4
Part No : PSP-JT13-700-M10
Part No : PXKT6
Part No : R-8100-20-T
Part No : R04 - P2M
Part No : R04 - P8M
Part No : R04 - R2F
Part No : R04 - R8F

ADAMS INTERNATIONAL LLC USA 1275 Bloomfield Ave Unit 81 Fairfield 07004, New Jersey, the United States Phone : +1 (973) 228-4293 Fax: +1 (973) 858-0288 E-Mail: info@adamsint.net Web: <http://www.adamsllc.net/>

Get quote now ! info@adamsint.net

Part No : RB5025A5
Part No : RBTMFA1H5-60-30-F30-G10-N10
Part No : RBXN-D40-L20-V13
Part No : RGEAHL2.0-500-Z-A20-B60-C60
Part No : S-PINGAUGECASE
Part No : SB40UU
Part No : SBCPS6-16
Part No : SBCPS6-20
Part No : SBTEH17
Part No : SCLBR20-141
Part No : SCPW21-8-8
Part No : SCSAB25-15
Part No : SCSJ50-18
Part No : SCSP8-10
Part No : SCSS7025C
Part No : SEBD16-230
Part No : SEBSZ10L-155
Part No : SELATAB8-P5.9-B5-A60
Part No : SFAM10-60-F23-B20-P8-T23-S20-Q8-SC0
Part No : SFAZ16-800-F18-B15-P10-NSC8-SC0
Part No : SFB3-8
Part No : SFGSMW0.02
Part No : SFJC12-115-M8-SC10
Part No : SFJZ10-66-M4-N4-SC15
Part No : SFJZ30-175-M16-N16-SC25
Part No : SFUD16-800-F18-B15-PMC10-NSC8
Part No : SHAMN20
Part No : SHASS30
Part No : SHFML20
Part No : SHFU8-P12-Q4-K8-L10-B7
Part No : SHFZ10-10
Part No : SHFZ10-12
Part No : SHMWM20-20
Part No : SLC03-000J
Part No : SLC06-000J

ADAMS INTERNATIONAL LLC USA 1275 Bloomfield Ave Unit 81 Fairfield 07004, New Jersey, the United States Phone : +1 (973) 228-4293 Fax: +1 (973) 858-0288 E-Mail: info@adamsint.net Web: <http://www.adamsllc.net/>

Get quote now ! info@adamsint.net

Part No : SLMUWS8
Part No : SMH20
Part No : SMKB8-10
Part No : SMS2-30L
Part No : SMSB6.5-10
Part No : SMTH 28
Part No : SMTP28
Part No : SNP03-000F
Part No : SNP08-000F
Part No : SOB-253350
Part No : SP40B-15-12
Part No : SP40B12-12
Part No : SPA01-000J
Part No : SPA02-000J
Part No : SPA03-000J
Part No : SPA04-000J
Part No : SPA06-000J
Part No : SPB-202815
Part No : SPB-202825
Part No : SPM-M12
Part No : SPP-1.6-10
Part No : SPP-2-24
Part No : SS40E2-L1-10
Part No : SS60E3-L4-10
Part No : SSB-M16X60-A
Part No : SSEBLT8-45
Part No : SSEBLV10-43
Part No : SSELB13-120
Part No : SSFHZ20-250-M8-N8-H30
Part No : SSFJT16-250-M8-SC10
Part No : SSFJW40-430-M12-N12
Part No : SSFR8-24.0
Part No : SSS02-020J
Part No : SSS03-040J
Part No : SSTEh10B

ADAMS INTERNATIONAL LLC USA 1275 Bloomfield Ave Unit 81 Fairfield 07004, New Jersey, the United States Phone : +1 (973) 228-4293 Fax: +1 (973) 858-0288 E-Mail: info@adamsint.net Web: <http://www.adamsllc.net/>

Get quote now ! info@adamsint.net

Part No : SSTE H14
Part No : SSTE H17B
Part No : ST-203K2S
Part No : STAM20-150-MN
Part No : STAM20-240-MN
Part No : STEHN10
Part No : STEHN13
Part No : SUS1.5-36
Part No : SUTP6A-275
Part No : SUTP6A-345
Part No : SUTPS6A
Part No : SWF20-100
Part No : SWF20-125
Part No : SWF20-65
Part No : SWF30-45
Part No : SWF30-60
Part No : SWF35-125
Part No : SWF60-400
Part No : SWM12-20
Part No : SWU10.5-75
Part No : SWU12.5-60
Part No : SX2RJ28-220
Part No : SXPAN16L
Part No : SXPKN12
Part No : SXPP8-4
Part No : SZU6-16
Part No : TAM4-015LG120
Part No : TB SA133AGSE-S02A0220A_MOTOPOSUNIT
Part No : TB_72010_47380_C_4_1_M4_03_04_2015
Part No : TB_72010_47380_C_4_1_M4_SOL_03_04_2015
Part No : TELATD6-P6.9-B15
Part No : THNTAN16-P24.9-B20-L20
Part No : THNTAN20-P32.9-B30-L20
Part No : THUPTAB10-P7.7-B20-T10-H18-A60
Part No : THUPTAB10-P8.9-B10-T10-H18-A60

ADAMS INTERNATIONAL LLC USA 1275 Bloomfield Ave Unit 81 Fairfield 07004, New Jersey, the United States
Phone : +1 (973) 228-4293 Fax: +1 (973) 858-0288 E-Mail: info@adamsint.net Web: <http://www.adamsllc.net/>

Get quote now ! info@adamsint.net

Part No : TLANARR8-P7.5-B50-L5-SC
Part No : TLATAN10-P10.1-B8-RC60
Part No : TLATAN10-P7.6-B6-RC60
Part No : TLATAN10-P7.9-B10
Part No : TLATAN10-P7.9-B12
Part No : TLATAN10-P7.9-B6-RC60
Part No : TLATAN10T-P9_5-B5-RC120
Part No : TLATAN10T-P9_5-B6-RC120
Part No : TLATAN8-P6_9-B5-RC90
Part No : TLATAN8-P7.3-B10-KD
Part No : TLATAN8-P7.9-B5-RC60
Part No : TLATAN8-P7.9-B5-RC90
Part No : TLATAN8-P8.1-B10-KD
Part No : TLATAN8-P8.1-B10-KD-RC60
Part No : TLATAN8-P8_1-B5-RC9
Part No : TLATDN10-B7.9-B7-KC-RC60
Part No : TLATDN10-P10.1-B8-RC60
Part No : TLATDN10-P11.9-B10-RC90
Part No : TLATDN10-P5.9-B9-KC
Part No : TLATDN10-P5.9-B9-KC-RC60
Part No : TLATDN10-P6.8-B7-KC-RC60
Part No : TLATDN10-P7.9-B10-KC
Part No : TLATDN10-P7.9-B12-KC
Part No : TLATDN10-P7.9-B6-RC60
Part No : TLATDN10-P7.9-B7-KC
Part No : TLATDN10-P7.9-B9-RC60
Part No : TLATDN8-P7.8-B12-RC60
Part No : TLATDN8-P7.9-B5-RC60
Part No : TSBXA40H
Part No : TSLATAA10-P9.9-B10-A60-E1
Part No : TSLATAA8-P6.9-B9-A60-E1
Part No : TSLATAA8-P7.3-B10-A60-E1
Part No : TSLATAA8-P8.4-B18-A60-E1
Part No : TSLATDA10-P9.9-B10-A60-E3-KC
Part No : TSLATDA8-P6.9-B9-A60-E1

ADAMS INTERNATIONAL LLC USA 1275 Bloomfield Ave Unit 81 Fairfield 07004, New Jersey, the United States
Phone : +1 (973) 228-4293 Fax: +1 (973) 858-0288 E-Mail: info@adamsint.net Web: <http://www.adamsllc.net/>

Get quote now ! info@adamsint.net

Part No : Timing belt L 050 PU

Part No : UMBRH6-28

Part No : UNUTSZ6

Part No : UPCN21-B-36

Part No : URLL16

Part No : URSL16

Part No : UWAN10-110-50

Part No : UWUAN94-N

Part No : VFJC8-60-M4-SC10

Part No : WH14-40

Part No : WH18-60

Part No : WL27-30

Part No : WSJM-D20-V10-T2

Part No : WSSB12-5-1

Part No : WSSB25-8-5

Part No : WSSB30-12-5

Part No : WSSB35-10-5

Part No : WT18-45

Part No : WYR1C- 0505D4

Part No : X-SWR39-45

Part No : XEG60

Part No : YCPF46F